

From jay at kk5im.com Mon Oct 9 14:49:42 2023  
From: jay at kk5im.com (jay at kk5im.com)  
Date: Mon, 09 Oct 2023 08:49:42 -0600  
Subject: [BoatAnchors] SCR-543-D (BC-669) Video Posted on YouTube  
Message-ID: <b471d83ca6d15bf142fe9eb327ca0bab@kk5im.com>

Check out my restoration of a complete SCR-543-D set up!  
Hope you enjoy it!

<https://youtu.be/JqutxonxpQ8>

73 de KK5IM

--

---

Jay H. Miller - KK5IM  
Trinity Graphics Systems  
Crawford, Texas  
[www.qrz.com/db/KK5IM](http://www.qrz.com/db/KK5IM) [1]  
My YouTube Channel:  
<https://www.youtube.com/@Radiotexas>

Links:

-----

[1] <http://www.qrz.com/db/KK5IM>

From arc5 at ix.netcom.com Mon Oct 9 16:00:22 2023  
From: arc5 at ix.netcom.com (David Stinson)  
Date: Mon, 9 Oct 2023 11:00:22 -0500  
Subject: [BoatAnchors] SCR-543-D (BC-669) Video Posted on YouTube  
In-Reply-To: <b471d83ca6d15bf142fe9eb327ca0bab@kk5im.com>  
References: <b471d83ca6d15bf142fe9eb327ca0bab@kk5im.com>  
Message-ID: <6f939470-80b8-4670-96be-de5763edb48d@ix.netcom.com>

Thank you kindly for sharing this. Wonderful work.  
The -669 is a favorite of mine.

73 DE Dave AB5S

On 10/9/2023 9:49 AM, jay at kk5im.com wrote:

>  
> Check out my restoration of a complete SCR-543-D set up!  
> Hope you enjoy it!  
>  
> <https://youtu.be/JqutxonxpQ8>  
>  
> 73 de KK5IM  
>

--

This email has been checked for viruses by Avast antivirus software.  
www.avast.com

From arc5 at ix.netcom.com Mon Oct 30 02:05:13 2023  
From: arc5 at ix.netcom.com (David Stinson)  
Date: Sun, 29 Oct 2023 21:05:13 -0500  
Subject: [BoatAnchors] German WWII Siemens K32 GWB Tubes  
Message-ID: <42953356-09be-4682-8b94-3e5ce71e334a@ix.netcom.com>

WWII German Siemens KG32 GWB Luftwaffe Morale Receiver.

Photos:

<https://photos.app.goo.gl/yoGkPfrfhYKoZqCo6>

The schematic in the photos lists valves:

ECH11, EF11, EBF11, 4SH1, EZ11

Another reference lists:

DCH11, DF11, DAF11, DY11

Are they really all Cold-Cathode valves?

Is there someone with experience on this radio?

Where can one find these valves?

TNX OM ES 73 DE Dave AB5S

--

This email has been checked for viruses by Avast antivirus software.  
www.avast.com

From john.shriver at gmail.com Mon Oct 30 02:17:05 2023  
From: john.shriver at gmail.com (John Shriver)  
Date: Sun, 29 Oct 2023 22:17:05 -0400  
Subject: [BoatAnchors] German WWII Siemens K32 GWB Tubes  
In-Reply-To: <42953356-09be-4682-8b94-3e5ce71e334a@ix.netcom.com>  
References: <42953356-09be-4682-8b94-3e5ce71e334a@ix.netcom.com>  
Message-ID: <7F0399F8-FF27-4773-AAC8-62AE90043F2F@gmail.com>

There appears to be a 6.3V filament winding on the transformer, along with some dropping resistors for the 4 volt filament of the output pentode.

Leading letter E on european tubes means 6.3V filament. D indicates 4V filament ? maybe later versions had a 4 volt filament winding.

Those tubes are out there for sale, mostly pricey. German metal tubes with a funky base.

> On Oct 29, 2023, at 10:05 PM, David Stinson via BoatAnchors <boatanchors at lists.theporch.com> wrote:  
>  
> WWII German Siemens KG32 GWB Luftwaffe Morale Receiver.  
> Photos:  
> <https://photos.app.goo.gl/yoGkPfrfhYKoZqCo6>  
>  
> The schematic in the photos lists valves:  
> ECH11, EF11, EBF11, 4SH1, EZ11  
>  
> Another reference lists:  
> DCH11, DF11, DAF11, DY11  
>  
> Are they really all Cold-Cathode valves?  
>  
> Is there someone with experience on this radio?  
> Where can one find these valves?  
>  
> TNX OM ES 73 DE Dave AB5S  
>  
>  
>  
> --  
> This email has been checked for viruses by Avast antivirus software.  
> www.avast.com  
> -----  
> BoatAnchors mailing list  
> BoatAnchors at lists.theporch.com  
> <https://lists.theporch.com/mailman/listinfo/boatanchors>

From vilgotch1 at gmail.com Mon Oct 30 05:54:01 2023  
From: vilgotch1 at gmail.com (Morris Odell)  
Date: Mon, 30 Oct 2023 16:54:01 +1100  
Subject: [BoatAnchors] German WWII Siemens K32 GWB Tubes  
In-Reply-To: <42953356-09be-4682-8b94-3e5ce71e334a@ix.netcom.com>  
References: <42953356-09be-4682-8b94-3e5ce71e334a@ix.netcom.com>  
Message-ID:  
<CAHhFqSk4535\_C2wZezCUb3toJ4gxxkEOpPU4aRFiykqcLmyrbQ@mail.gmail.com>

Hi Dave,

They are not cold cathode, they're just drawn that way. The dot electrode is the cathode. There's what looks like a low voltage secondary on the power transformer for the heaters

Those valves would be pretty scarce and hard to find.

73, Morris VK3DOC

On Mon, 30 Oct 2023 at 1:04 pm, David Stinson via BoatAnchors <boatanchors at lists.theporch.com> wrote:

> WWII German Siemens KG32 GWB Luftwaffe Morale Receiver.  
> Photos:  
> <https://photos.app.goo.gl/yoGkPfrfhYKoZqCo6>  
>  
> The schematic in the photos lists valves:  
> ECH11, EF11, EBF11, 4SH1, EZ11  
>  
> Another reference lists:  
> DCH11, DF11, DAF11, DY11  
>  
> Are they really all Cold-Cathode valves?  
>  
> Is there someone with experience on this radio?  
> Where can one find these valves?  
>  
> TNX OM ES 73 DE Dave AB5S  
>  
>  
>  
> --  
> This email has been checked for viruses by Avast antivirus software.  
> www.avast.com  
> -----  
> BoatAnchors mailing list  
> BoatAnchors at lists.theporch.com  
> <https://lists.theporch.com/mailman/listinfo/boatanchors>  
>

From k1lky68 at gmail.com Tue Oct 31 08:32:20 2023

From: k1lky68 at gmail.com (Roy Morgan)

Date: Tue, 31 Oct 2023 04:32:20 -0400

Subject: [BoatAnchors] German WWII Siemens K32 GWB Tubes

In-Reply-To: <42953356-09be-4682-8b94-3e5ce71e334a@ix.netcom.com>

References: <42953356-09be-4682-8b94-3e5ce71e334a@ix.netcom.com>

Message-ID: <D612F64F-72BA-41CC-B33F-FF996C459916@gmail.com>

I see "N.G." On the valves - when I mark something that way it means "No Good". Hoping you can find replacements or a workaround (filament equivalents maybe).

Roy Morgan  
K1LKY Western Mass  
K1LKY68 at gmail.com

> On Oct 29, 2023, at 10:04 PM, David Stinson via BoatAnchors <boatanchors  
at lists.theporch.com> wrote:  
>  
> ?WWII German Siemens KG32 GWB Luftwaffe Morale Receiver.  
> Photos:  
> <https://photos.app.goo.gl/yoGkPfrfhYKoZqCo6>  
>  
> The schematic in the photos lists valves:  
> ECH11, EF11, EBF11, 4SH1, EZ11  
>  
> Another reference lists:  
> DCH11, DF11, DAF11, DY11  
>  
> Are they really all Cold-Cathode valves?  
>  
> Is there someone with experience on this radio?  
> Where can one find these valves?  
>  
> TNX OM ES 73 DE Dave AB5S  
>  
>  
>  
> --  
> This email has been checked for viruses by Avast antivirus software.  
> [www.avast.com](http://www.avast.com)  
> -----  
> BoatAnchors mailing list  
> BoatAnchors at lists.theporch.com  
> <https://lists.theporch.com/mailman/listinfo/boatanchors>